

## Report for Hanspukuria Gram Panchayat , Tehatta-II Block , Nadia District

Sl. No.	Attribute	
1.	Total Stand posts in Hanspukuria Gram Panchayat	64 nos
2.	Total working stand posts in Hanspukuria Gram Panchayat	53 nos
3.	Total Not working stand posts in Hanspukuria Gram Panchayat	11 nos
4.	Total Valve in Hanspukuria Gram Panchayat	26 nos
5.	Total sluice valve in Hanspukuria Gram Panchayat	25 nos
6.	Total air valve in Hanspukuria Gram Panchayat	0 nos
7.	Total scour valve in Hanspukuria Gram Panchayat	1 nos
8.	Total water quality (Arsenic) tested in Tehatta-II Block	458 nos
9.	Total water quality (Iron) tested in Tehatta-II Block	458 nos
10.	Arsenic value > 0.05	29 nos
11.	Arsenic value <= 0.05	429 nos
12.	Iron value > 1	365 nos
13.	Iron value <= 1	93 nos
14.	Total Laboratoris in Tehatta-II Block	0 nos
15.	Total School in Hanspukuria Gram Panchayat	18 nos