

Report for Bagula-ii Gram Panchayat , Hanskhali Block , Nadia District

Sl. No.	Attribute	
1.	Total Stand posts in Bagula-ii Gram Panchayat	97 nos
2.	Total working stand posts in Bagula-ii Gram Panchayat	83 nos
3.	Total Not working stand posts in Bagula-ii Gram Panchayat	14 nos
4.	Total Valve in Bagula-ii Gram Panchayat	18 nos
5.	Total sluice valve in Bagula-ii Gram Panchayat	18 nos
6.	Total air valve in Bagula-ii Gram Panchayat	0 nos
7.	Total scour valve in Bagula-ii Gram Panchayat	0 nos
8.	Total water quality (Arsenic) tested in Hanskhali Block	0 nos
9.	Total water quality (Iron) tested in Hanskhali Block	0 nos
10.	Arsenic value > 0.05	0 nos
11.	Arsenic value <= 0.05	0 nos
12.	Iron value > 1	0 nos
13.	Iron value <= 1	0 nos
14.	Total Laboratoris in Hanskhali Block	1 nos
15.	Total School in Bagula-ii Gram Panchayat	26 nos