

Report for Saktipur Gram Panchayat , Beldanga-II Block , Murshidabad District

Sl. No.	Attribute	
1.	Total Stand posts in Saktipur Gram Panchayat	59 nos
2.	Total working stand posts in Saktipur Gram Panchayat	18 nos
3.	Total Not working stand posts in Saktipur Gram Panchayat	41 nos
4.	Total Valve in Saktipur Gram Panchayat	4 nos
5.	Total sluice valve in Saktipur Gram Panchayat	4 nos
6.	Total air valve in Saktipur Gram Panchayat	0 nos
7.	Total scour valve in Saktipur Gram Panchayat	0 nos
8.	Total water quality (Arsenic) tested in Beldanga-II Block	1416 nos
9.	Total water quality (Iron) tested in Beldanga-II Block	1416 nos
10.	Arsenic value > 0.05	325 nos
11.	Arsenic value <= 0.05	1091 nos
12.	Iron value > 1	969 nos
13.	Iron value <= 1	447 nos
14.	Total Laboratoris in Beldanga-II Block	1 nos
15.	Total School in Saktipur Gram Panchayat	28 nos